


FIG. 1

Organic insulating layer pattern  
from glass substrate surface  
- occurrence of a peeling



Organic insulating layer pattern on ITO surface  
- no occurrence of a peeling

FIG. 2




FIG. 3A






FIG. 3D




FIG. 3E




FIG. 4A




FIG. 4B

